



Official Laboratory Report

Report To: JOHN ORR
 36479 S WHITNEY BAY
 DRUMMOND ISLAND MI 49726

System Name/Owner:	WHITE FISH TWP SCHOOL	WSSN/Pool ID:	20000217
Collection Address:	7221 N M123,PARADISE	Source:	TYPE II
Collected By:	JOHN ORR	Site Code:	
Township/Well#/Section:	PARADISE//	Collector:	Public Water Supply Operator
County:	Chippewa	Date Collected:	05/16/2017 09:15
Sample Point:	TANK TAP	Date Received:	05/17/2017 10:44
Water System:	Pressure Tank/Plant Tap	Purpose:	Routine Monitoring

Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Chloride	Not detected	05/17/2017	4		SM 4500-Cl E	7647-14-5
Fluoride	Not detected	05/17/2017	0.1	4.0	SM 4500 FC	16984-48-8
Hardness as CaCO3	116	05/17/2017	20		SM 2340 C	HARD-00-C
Iron (automated)	0.2	05/17/2017	0.1		SM 3500 FeB	7439-89-6
Nitrate as N	Not Detected	05/17/2017	0.4	10	10-107-04-2-B	14797-55-8
Nitrite as N	Not detected	05/17/2017	0.05	1	10-107-04-2-B	14797-65-0
Sodium (automated)	Not detected	05/17/2017	5		SM 3500 NaB	7440-23-5
Sulfate	Not detected	05/17/2017	10		SM 4500 SO4E	14808-79-8

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Chippewa County Health Dept.
 508 Ashmun, Suite 120
 Sault Sainte Marie, MI 49783
 906 635-3620**

CAS#: Chemical Abstract Service Registry Number	mg/L : milligrams / Liter (ppm)	Laboratory Contact:
MCL : Maximum Contaminant Level	ppm : parts per million	Drinking Water Unit Mgr: Julia Pieper
AL : Action Level	MPN : Most Probable Number	
RL : Reporting Limit	CFU : Colony Forming Unit	